

PENNZOIL PLACE • P. O. BOX 2967 • HOUSTON, TEXAS 77252-2967 • (713) 546-8886

Vernou Solid wast

ANTHONY B. CAVENDER Attorney

August 1, 1984

Mr. David Storm State of California Hazardous Waste Division 714/744 P Street Sacramento, California 95814

> Re: Waste Classification Form Pennzoil Products Company of Vernon, California

Dear Mr. Storm:

On behalf of Pennzoil Products Company of Vernon, California, the above-referenced waste classification form is submitted for your review.

You will recall that Ms. Usha Mehra of Pennzoil Company's Environmental Safety and Health Division informed you that insignificant traces of hazardous constituents were found in samples of the solid waste generated by our Vernon, California, facility.

The completed waste classification form and its attachments provide a description of the analytical tests performed on this waste and the concentrations in which these hazardous constituents were found. The tests were conducted by Smith-Emery Company of Los Angeles, California, on April 19, 1984, and May 31, In accordance with the guidelines followed by your agency, the wastes generated by the Vernon, California, facility of Pennzoil Products Company are not considered regulated hazardous wastes.

In view of the urgent necessity to arrange for the safe and expeditious disposal of solid waste which has accumulated at our Vernon facility, our plant manager, Mr. James Waldrip, has not signed the form's certification at page 6. However, this form has been prepared with the advice and counsel of Mr. Waldrip, and we shall obtain his signed certification for your records as soon as possible. In his absence, and with his consent, Ms. Usha Mehra has signed this certification.



Mr. David Storm

-2-

August 1, 1984

As Ms. Mehra advised you, we would appreciate a prompt response to this notification, whether by telephone or letter. Thank you for your assistance.

Very truly yours,

Anthony B. Cavender

ABC:jb

Enclosures

cc: Ms. Usha Mehra

Mr. James Waldrip

WASTE CLASSIFICATION FORM

- 1. Name and Address of Waste Facility.
 - Mailing address.
 Pennzoil Products Company
 3430 East 26th St. Vernon, CA 90023
 - Location at which waste is generated, if different from above.
 Same as (a)
 - Contact person and phone number. James Waldrip (213)385-0311
- 2. Description of Waste:
 - a. Physical description. Clarifier Waste - liquid slurry Grease Pit Waste - slurry
 - b. Quantities produced per unit time. Clarifier Waste approximately 3500 gallons/3 months Grease Pit Waste approximately 3500 gallons/4 months
 - c. Process used to generate waste. See Attachment #1
 - d. Present method of waste disposal. Land disposal (offsite)
- Sampling Information:
 - Name and address of company that sampled the waste.
 Same as 1(a)

(rev: FO3 9/83)

- b. Name of person(s) who sampled the waste.
 Mr. Henry Lebseme
- c. Dates and locations of collected samples:

TYPE OF SAMPLE COLLECTED	LOCATION	DATE COLLECTED	FIELD SAMPLE NO.
Composite of several grab samples	Clarifier	4/19 - 5/31	Clarifier sample
Composite of several grab samples	Grease pit	4/19 - 5/31	Grease Pit Sample

- d. Description of sampling methodology:
 - (1) Sampling technique at site or facility.

A representative sample of waste was obtained by stirring the pit waste, grabbing approximately 5 samples from the pit, and obtaining a sample from mixing the individual grabs in a 5 gallon plastic container. Sampling for clarifier pit and grease pit were done in a similar manner.

(2) Sample handling and preservation prior to laboratory analysis.

The samples were immediately taken to the laboratories for analyses, therefore no sample preservation was done at site.

- 4. Testing Laboratories Information: See Attachment #2
 - a. Name and address of laboratories:

Smith-Emery Company 781 East Washington Blvd. Los Angeles, CA 90021

b. Test methods and references: See Attachment #2

METHOD*	REFERENCE
s	
3	

SPECIFIC TEST	METHOD*	REFERENCE
norganic Analysis, Metallic (c	ontinued)	
- Copper		
- Lead, inorganic		
- Lead, organic		
- Mercury		
- Molybdenum		
- Nickel		
- Selenium		
- Silver		·
- Thallium		
- Vanadium	•	,
- Zinc		
- Other (Specify)		
. Inorganic Analysis, Non-Met	allic	- - :
- Total cyanide		
- Cyanide (chlorination)		<u>- </u>
- Fluoride		
- Sulfide		
- Asbestos		
- pH		
- Free liquids		
- 'Other (specify)		
. Special Tests		
- California Waste		
Extraction Test - Tests for Hazardous Properties	Sec. 66700	
- Aquatic 96 hr LC ₅₀		
- Flashpoint		
- Corrosivity		
- Head Space	Sec. 66696(a)(10)	· · · · · · · · · · · · · · · · · · ·
- Other (specify)		

^{*} If this is not a standard method (APHA-AWWA-WPCF, ASTM, AOAC, EPA, etc) please attach a copy of method with this report.

c.	Names	and	qualifications	of	persons	testing	waste.
~ •	1.4001115-3	G 114	AAM***********************************	~1	D-130113	r - 3 + 1 1 1 1	MEDIC:

d. Preparation of laboratory samples from field samples.

e. Sample identification information:

TYPE OF SAMPLE TESTED	FIELD SAMPLE NO(S)	LABORATORY SAMPLE NO.	DATE TESTED
			-
		<u> </u>	
	<u> </u>		
			
<u></u>	·		

5.	Qualit	y Assurance and Control: (See Appendix I) N/A
	a.	On file with the DOHS Hazardous Materials Laboratory;
		yes no
	ь.	Enclosed; yes;
	ç.	Will be forwarded to DOHS by;
6.	Labora	atory Results See the attached reports. (See Attachment #2)
	a.	Waste Components and California Waste Extraction Test Summary (Form 1).
	ь.	Aquatic Bioassay. Use California Department of Fish Bioassay Data Sheet.
	c.	Submission of Data and Reports (See Appendix 1).
7.	Acute	toxicity calculations from published data: (Form 2)
8.	Corros	sivity, Flammability, Reactivity (Form 3)
9.	Refere	ences (Attach complete citations)
i0.	Certif	ication by person(s) who is the responsible manager of the facility.
		"I certify under penalty of law that I have personally examined and am familiar with the information submitted in this notification and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment."
Signatu		Usha mehra Date July 31, 1984
Printed		
Title	Envio	omental Advisor - Pennzoil Company

Attachment #1

2.C Process Used to Generate Waste

Clarifier Waste

The clarifier waste is generated from a drum cooperage operation at Pennzoil's Vernon plant. The cooperage operation includes a drum washing step which generates a liquid waste stream. This waste is stored in a clarifier tank where the solids from the washings settle down in the tank and the supernatant is discharged to the city's waste water treatment plant. With time, the bottom sludge builds up and is disposed offsite as clarifier waste.

Grease Pit Waste

The grease pit waste is generated primarily from used grease drums before they are shipped to an offsite drum cooperage facility. The residual grease in used drums is removed and stored in the grease pit. The spent floor scrubber solution, used for housecleaning at the plant, is also stored in the grease pit. These two wastes together, consitutue the grease pit waste.

SMITH-EMERY COMPANY

An Independent Commercial Testing Laboratory Established 1904

THE EAST WASHINGTON BOULEVARD . LOS ANGELES, CALIFORNIA 90021 . (213) 749-3411

ALL RESPONS ARE SUBMITIVED AS THE CONFIDENTIAL PROPERTY OF CHIESTS, ACTIONIZATION FOR PROJECTION OF DUB REPORT, CONCLUSIONS OR EXTRACTS FROM OR REGARDING THEM IS RENEIVED PENDING OF IN RITTEN APPROXIALAS AND TEACH PROPERTIES OF CLEAMS, THE PUBLIC AND OF THE LOSS.

FILL NO.

7159

DATE

MAY 7, 1984

LABORATORY NO.;

590410

FOR.

PENNZOIL PRODUCTS COMPANY 1630 WEST OLYMPIC BOULEVARD LOS ANGELES, CALIFORNIA 90015

ATTENTION:

JAMES WALDRIP

SUBJECT:

WASTE DIL ANALYSIS - P.O.# 43240-CE

SAMPLE:

LIQUID WASTE FROM CLARIFIER AND GREASE PIT AT

3430 EAST 26TH STREET, VERNON, CALIFORNIA

PROCEDURE:

STANDARD METHODS - A.P.H.A.

		•
RESULTS:	A4464	A4465
	<u>Clarifier</u>	<u>Grease Pit</u>
FLASH POINT, ASTM D-93, *	F. >200	166
PH (50% SLURRY WITH WATER), UNITS 9.4	6.7
ARSENIC, PPM	0.16	0.13
CADMIUM, PPM	0.74	0.69
CHROMIUM, PPM	5.7	11.7
LEAD, PPM	4.7	17.7
MERCURY, PPM	<0.39	<0.36
NICKEL, PPM	2.3	2.3
SELENIUM, PPM	<0.19	<0,18
THALLIUM, PPM	<1.9	₹1.8
CYANIDE, PPM	<0.1	<0.1
SULFIDE, PPM	N.D.	N.D.
CHLORINATED HYDROCARBONS.	<u>PPM</u>	
1.2-DICHLOROETHANE	26.0	5.6
TRICHLORDETHENE,	0.086	6.6
	N.D. = NOT DETERMINED	

RESPECTFULLY SUBMITTED,

SMITH-EMERY COMPANY

P. E. MATHENY, MANAGER CHEMICAL LABORATORY

PQS2 02115

HI MISTS . TO LING . INSPECT N. . ENGINGERS



SMITH-EMERY COMPANY An Independent Commercial Testing Laboratory Established 1904 781 EAST WASHINGTON BOULEVARD . LOS ANGELES, CALIFORNIA 80021 . (213) 749-3411

ALL REPORTS ARE SUBMITTED AS THE CONFIDENTIAL PROPERTY OF CHENES, ARTHORIZATION FOR PUBLICATION OF QUE REPORT, CONCLUSIONS, OR EXTRACTS PROMOB REGARDING THEM IS RESERVED PENDING OUR WRITTEN APPROVALAS A MUTUAL PROTECTION TO CLIENTS. THE PUBLICAND OUR SELVES.

FILE NO: LABORATORY NO: 7159

DATE JUNE 7, 1984

590560

FOR:

PENNZOIL PRODUCTS COMPANY
1630 WEST OLYMPIC BOULEVARD
LDS ANGELES, CALIFORNIA 9001S

ATTENTION:

JAMES WALDRIP

SUBJECT:

LIQUID WASTE ANALYSIS - P.O.# 43283-C.E.

SAMPLE:

ONE QUART SAMPLE FROM CLARIFIER, ONE QUART SAMPLE

FROM GREASE PIT RECEIVED 5/31/84

PROCEDURE:

STANDARD METHODS, 15TH EDITION, A.P.H.A.

RESULTS:

	CLARIFIER	GREASE PIT
CADMIUM, PPM	<0.26	0.98
CHROMIUM. PPM	7.12	7.81
LEAD, PPM	9.87	7.92
NICKEL, PPM	0.39	2.46

CHLORINATED HYDROCARBONS, (C1 - C6), PPM

•		
METHYLENE CHLORIDE	32.	<0.01
CHLOROFORM	0.29	0.21
1,1,1-TRICHLORD ETHANE	<0.01	2.4
TRICHLORG ETHYLENE	<0.01	19.
TETRACHLORO ETHYLENE	<0.01	0.13

RESPECTFULLY SUBMITTED,

SMITH-EMERY COMPANY

P. E. MATHENY, MANAGER CHEMICAL VABORATORY

^PQS2 02116